



99A ★ EQUIPMENT DESCRIPTION:
SINGLE SHIELD, RAMS AND HOSES REMOVED.
NO REMAINING FLUIDS. ABANDONED 6/95.

99B ★ EQUIPMENT DESCRIPTION:
CONVEYOR BELT TAIL, STEEL AND RUBBER
ONLY. NO REMAINING FLUIDS. ABANDONED
12/98.

99C ★ EQUIPMENT DESCRIPTION:
LONGWALL EMULSION TANK, 3000 GAL.
CAPACITY. NO REMAINING FLUIDS.
ABANDONED 12/98.

99D ★ EQUIPMENT DESCRIPTION:
FOUR LONGWALL SHIELDS, USEABLE PARTS
REMOVED. EMULSION REMOVED. NO
REMAINING FLUIDS. ABANDONED 12/98.


01A ★ EQUIPMENT DESCRIPTION:
LONGWALL FACE CONVEYOR. 160 PAN
SECTIONS. NO FLUIDS OF HOSES REMAIN.
STEEL ONLY. ABANDONED 4/01

04A ★ EQUIPMENT DESCRIPTION:
121 EACH DOWTY AND K-B ROOF SUPPORTS
(SHIELDS). LONGWALL FACE CONVEYOR
COMPLETE WITH LINE PANS, SPECIAL PANS,
TAILGATE DRIVE, AND STAGELoader.

04B ★ EQUIPMENT DESCRIPTION:
APPROXIMATELY 82 K-B ROOF SUPPORT
SHIELDS BETWEEN XCUTS 22 AND 37, 6L B
PANEL. NO FLUIDS REMAIN. STEEL ONLY.
ABANDONED 3/04

08A ★ EQUIPMENT DESCRIPTION:
148 EACH GULLICK DOBSON SUPPORTS -
SHIELDS ONLY (EMULSION WAS DILUTED TO
97-100% WATER, ELECTRONICS, LIGHTS, AND
BATTERIES WERE REMOVED). ABANDONED
05/08

RECEIVED
APR 22 2008
DIV. OF OIL, GAS & MINING



REVISIONS	
DATE	BY
6/10/03	DEJ
5/12/04	CDH
5/02/04	CDH
4/14/08	G.G.
Added 08A, Changed Photo No from 2.3.6-3 Changed Equipment Cataloging, deleted 04A, Mining	

MINE 3 LEVELS 2 & 3
ABANDONED MINING EQUIPMENT LOCATIONS

Canyon Fuel Company, LLC
Skyline Mines

DATE: 6/09/03 OK BY: G. GALECKI
SCALE: NO SCALE DR BY: B. REES
DWG. NO: 2.5.2-1

File in:
☐ Confidential
☐ Shelf
☒ Expandable
Refer to Record No. 0032 Date 4/15/2008
In C:\007005-2008-Skyline.mxd
For additional information